

GENERAL NOTES

1. SEE OTHER SHEETS IN THIS SET FOR ADDITIONAL INFORMATION.

2. SEE SHEET T1.1 FOR TYPICAL GENERAL NOTES.
3. THE CLUBHOUSE IS CONSTRUCTED OF CEDAR LOGS RANGING IN APPROXIMATE DIAMETER FROM 6" TO 8½". THE LOGS ARE SET WITH TIGHT JOINTS, LAPPED AND SPIKED AT THE CORNERS ("BUTT-AND-PASS JOINTS"). THE VERTICAL LOGS

GENERAL SCOPE OF WORK:

ARE FASTENED WITH SPIKES AT BASE AND TOP.

ALL THE WORK NOTED BELOW APPLIES TO ALL EXTERIOR WOOD SURFACES (LOGS, EXPOSED RAFTERS, AND TRIM):

1. SCRAPE CONCRETE SLURRY OFF OF ALL

EXTERIOR LOG SURFACES.

2. REMOVE SEALANT AND ROTTED WOOD FROM ALL JOINTS AND CHECKS.

3. REMOVE CONCRETE FILL AND ROTTED WOOD

FROM ALL HAIRLINE CRACKS. THIS APPLIES TO THE EXTERIOR OF ALL LOGS - EACH LOG HAS AN AVERAGE OF TWO FULL-LENGTH HAIRLINE CRACKS FILLED WITH CONCRETE.

4. REMOVE CONCRETE PATCHES AS IDENTIFIED IN ITEMIZED NOTES & AS INDICATED BY LEGEND.
5. INSERT BORATE RODS INTO ALL CROWN ENDS AND PLUG WITH PT WOOD DOWEL. SEE 19/A1.3.
6. STRIP PAINT FROM EXTERIOR OF LOGS AND WINDOW TRIM (OF ALL 3 FLOORS), THEN CLEAN AS SPECIFIED. COAT ALL EXTERIOR SURFACES OF LOGS AND WINDOW TRIM WITH BORATE SOLUTION, & WATER REPELLENT PRESERVATIVE STAIN FINISH.

7. AFTER APPLICATION OF PAINT SYSTEM, PACK OAKUM INTO ALL INTERIOR & EXTERIOR JOINTS IMPACTED BY LOG RESTORATION, AND INTO CHECKS THAT FACE UP.

8. WHERE REPLACING PORTION OF LOG AT CORNER, SEE DETAILS 15 & 16/A1.3.

8. WHERE REPLACING PORTION OF LOG AT CORNER, SEE DETAILS 15 & 16/A1.3.
9. SEE SPECIFICATIONS ON SHEET A1.3 FOR PRODUCTS AND APPLICATIONS.

REPAIR LEGEND:

SEE DETAILS ON SHEET A1.3.

INSERT BORATE IMPEL ROD INTO END OF CROWN. DETAIL 19/A1.3.

REMOVE CONCRETE PATCH. PROVIDE WOOD DUTCHMAN (5/A1.3), ½ LOG FACE REPLACEMENT (6/A1.3), OR FULL LOG FACE REPLACEMENT (13/A1.3)

FACE REPLACEMENT (6/A1.3), OR FULL LOG FACE REPLACEMENT (13/A1.3) FOR AREA SHOWN.

REMOVE CONCRETE FROM LOG FACE.

REMOVE EXISTING & PROVIDE NEW

LOC

LOG FACE. DETAIL 13/A1.3.

REMOVE AVG. OF 3 CONCRETE
PATCHES PER LENGTH OF EACH
LOG SHOWN. REMOVE ROTTED
WOOD & WOOD AS REQ'D TO
PROVIDE FULL-LENGTH DUTCHMAN
FACE ACROSS TOP ½ OF LOG.

	1	<u> </u>	
	-	02/24/06	100% Construction Documents
		11/16/05	General Revisions
		10/26/05	50% CD Pricing
•	Rev.	Date	Issued for

Modifications T

Dune Acres Clubhouse

Exterior Log Restoration Clubhouse Road Dune Acres, Indiana



Gilmore Franzen Architects, Inc.

409 North Ridgeland Avenue Oak Park, Illinois 60302

ne: (708) 386-4620 Fax: (708) 386-4

Shed

Exterior Elevations

Date:
October 26, 2005
Project No.:
0518

Sheet No.:
A1.